


REPLACING THE CHAIN MAY NOT ALWAYS BE ENOUGH

Easily check your drive sprocket or chain ring and thus ensure that your chain is not unnecessarily strained by worn-out teeth.

If the wear indicator does not fully fit into the gap between two teeth and a small gap remains visible, the gearing is still in a good condition.



If the indicator is completely in contact and there is no gap, the sprocket/chain ring should be replaced together with the chain.

